

**On-car analysis list from October 21st, 2016  
please contact VW Helpline before attempting repair**

	<b>Models</b>	<b>MY</b>	<b>Engine</b>	<b>Transmission</b>	<b>Topic</b>	<b>Customer Complaint</b>
<b>Powertrain</b>	Tiguan	15	All	All	MIL-on P013E	MIL-on fault P013E in the ECM
	Golf R	16	All	All	Turbo Failure	Customer states noise from the engine/turbo
	Golf/GTI, Golf Sportwagen	15-17	All	All	Fuel Level Sensor (10/11/2016)	Fuel gauge not reading full after topping up the fuel <b>(untouched vehicles)</b> <b>(MUST have any of P0461/2/3 and/or B103E1A/B in ECM or Instrument cluster)</b>
	Tiguan, EOS, CC	16-17	All	All	Rear Main Seal Leak	Customer states oil leak <b>(untouched vehicles)</b>
	Passat	14-17	1.8T (CPKA/CPRA)	All	MIL-on P2407	MIL-on fault P2407 in the ECM <b>(untouched vehicles)</b>
	Golf/GTI, Golf Sportwagen	16-17	All	All	Fuel Line Noise	Fuel line rattle from below the vehicle <b>(untouched vehicles after VIN GM016333)</b>
<b>Chassis</b>	GTI	16	All	Standard	Clutch Pedal Noise	Clutch pedal squeal/squeak when operating clutch pedal
	Passat	15-16	All	All	Center Cap	Center cap missing after PDI <b>(more than 100 miles on the vehicle)</b>
<b>Body</b>	Passat	16	All	All	Instrument Panel Noise	Instrument panel noise <b>(untouched vehicles after VIN HC011431)</b>
	Passat	16-17	All	All	Parking Sensor	Parking Sensor Loose or Missing from Front/Rear Bumper
	Passat	16-17	All	All	Door Noise	Door(s) noise <b>(untouched vehicles after VIN GC052150 )</b>