





## Delivery Stop: Remove Engine Oil Label

New information provided by this revision is preceded by this symbol .

This Service Information bulletin and attachment supersedes SI B51 16 15 dated July 2015.

### MODEL

 I01 (i3 Rex)	 I12 (i8)	E84 (X1)	E89 (Z4 Roadster)
F01/02 (7 Series Sedan)	F06 (6 Series Gran Coupe)	F07 (5 Series Gran Turismo)	F10 (5 Series Sedan)
F12 (6 Series Convertible)	F13 (6 Series Coupe)	F15 (X5)	F16 (X6)
F22 (2 Series Coupe)	F23 (2 Series Convertible)	F25 (X3)	F26 (X4)
F30 (3 Series Sedan)	F31 (3 Series Sport Wagon)	F32 (4 Series Coupe)	F33 (4 Series Convertible)
F34 (3 Series Gran Turismo)	F36 (4 Series Gran Coupe)	F80 (M3 Sedan)	F82 (M4 Coupe)
F83 (M4 Convertible)	F85 (X5 M)	F86 (X6 M)	

### SITUATION

Affected vehicles in dealer inventory **must not be retailed** or delivered until the label is removed.

Vehicles at ports of entry will be remedied prior to dealer delivery.

On affected vehicles, there is an incorrect label regarding the appropriate engine oil.

Affected vehicles can be identified with a "Vehicle Comment" in the DCS Warranty Vehicle Inquiry or ISPA Light.

### CAUSE

--	--



The text on the label does not conform to legal regulations.

## CORRECTION

Remove the engine oil label (located in the front or rear of the hood).

## PROCEDURE

Remove the label using a hot air gun to soften the adhesive. Gently pull the label off while varying the heat. Remove any remaining adhesive with solvent-based cleaner.

Discard the removed label.

## WARRANTY INFORMATION

Reimbursement for this Service Action will be via normal claim entry utilizing the following information:

<b>Defect Code:</b>	<b>00 71 21 02 00</b>	
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 63 632	1 FRU	Remove engine oil label (Plus work)

## ADDITIONAL INFORMATION

Perform the procedure outlined in this Service Information on all affected vehicles before customer delivery or the next time they are in the shop for maintenance or repairs.

[ Copyright ©2015 BMW of North America, Inc. ]