



SI B33 04 16
Rear Axle

July 2016
Technical Service

Delivery Stop: Replace Rear Differential

MODEL

F06 (6 Series Gran Coupe)	F10 (5 Series Sedan incl. M5)	F12 (6 Series Convertible incl. M6)	F13 (6 Series Coupe incl. M6)
F80 (M3 Sedan)	F82 (M4 Coupe)	F83 (M4 Convertible)	F87 (M2 Coupe)

SITUATION

A Delivery Stop has been issued on certain M2 Coupe, M3 Sedan, M4 Coupe and Convertible, 5 Series Sedan (incl. M), 6 Series Gran Coupe, Convertible, and Coupe produced from May 12, 2016 through July 4, 2016. These vehicles will require a replacement of the rear differential.

Approximately 202 vehicles may be affected.

Affected vehicles can be identified soon under “Open Campaign” in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

STOP011633 Delivery Stop B330416 No repair available at this time.

This bulletin will be updated with repair instructions, parts and warranty information when they become available.

ATTACHMENTS

View PDF attachment [B330416 Delivery Stop Legal](#).

View PDF attachment [B330416 VIN list](#).

[Copyright ©2016 BMW of North America, Inc.]