



This Service Information bulletin supersedes SI 12 33 14 **dated December 2015**.

SUBJECT

Fault Code 1D2008 Stored in DME

MODEL

F22 (2 Series)

F25 (X3)

F26 (X4)

F30 (3 Series Sedan)

F32 (4 Series Coupe)

F33 (4 Series Convertible)

F34 (3 Series Gran Turismo)

F36 (4 Series Gran Turismo)

With automatic transmission

SITUATION

The Service Engine Soon light is on. Fault Code 1D2008: Map thermostat: jammed open is stored in the DME. There may also be a complaint of low heat output with lower outside temperatures.

CAUSE


During the engine warm-up, the engine coolant does not reach operating temperature within the DME's allowable time limits.

This is caused by either a faulty thermostat inside the transmission oil heat exchanger or a faulty engine characteristic map thermostat.

PROCEDURE

Note: The following checking procedure must be performed on a cold engine.

	<p>Remove the front underbody protection panel (tightening torque of screws is 3Nm) to access the cooling lines to the transmission oil heat</p>
--	--



exchanger (1).
(Note: All illustrations were taken on an F30 328xi N20).



Clamp off the outflow hose (1) on the cooler with special tool 81 64 2 184 117 (SI B04 07 11). The outflow hose is the softer (rubber) of the two cooling lines on the heat exchanger.



After clamping, remove the outflow hose from the heat exchanger (1).



Loosen the cap on the coolant expansion tank (1).



If any coolant starts leaking out of the transmission heat exchanger (1), the internal thermostat is jammed and the heat exchanger will need to be replaced.

Follow Repair Instruction RA 17 22 010, “Removing and installing/replacing transmission oil cooler for automatic transmission (N20, N26, N55).”

A TC PuMA case is no longer needed for parts replacement authorization.

If there is **no coolant loss** out of the heat exchanger, replace the engine coolant thermostat.

Follow Repair Instruction RA 11 53 000, “Removing and installing/replacing coolant thermostat.”

PARTS INFORMATION

Part Number	Description	Quantity
17 21 7 600 553	Heat exchanger (transmission 2,3 or 4 Series)	1*
17 21 7 593 856	Heat exchanger (transmission X3 and X4)	1*
Or:		

NEW 11 53 8 635 689	Thermostat (N20, N26)	1*
11 53 7 598 865	Thermostat (N55)	1*
NEW 11 53 7 586 784	Thermostat (N55) (X3 and X4)	1*

* If needed

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program.

Defect Code:	17 21 01 48 00	Heat exchanger, automatic transmission
Labor Operation:	Labor Allowance:	Description:
17 22 010	Refer to KSD2	Replacing heat exchanger for automatic transmission (Includes 00 11 237/500: checking/topping up automatic transmission fluid level which includes performing a Vehicle Test and charging the battery)
And:		
17 99 000	4 FRU	Work time for checking the function of the thermostat in the transmission heat exchanger

If you are using a Main labor code for another repair, use the Plus code labor operation 17 22 510 instead.

And, as needed:

Sublet – Bulk Materials

Sublet Code 4	See sublet reimbursement calculation below	Reimbursement for the used quantity of transmission fluid (Bulk container reference P/N 83 22 2 220 439 for 20 liters or P/N 83 22 2 220 443 for one liter). Please do not use these part numbers for claim submission.
---------------	--	---

Sublet calculation: Reimbursement for used quantities of transmission fluid (P/N 83 22 2 220 439 for 20 liters or P/N 83 22 2 220 443 for one liter) at dealer net plus handling.

Enter this material cost in sublet and itemize the amount in the claim comment section.

Or:

Defect Code:	11 53 12 96 00	Characteristic map thermostat
Labor Operation:	Labor Allowance:	Description:
00 00 006	Refer to KSD2	Performing “vehicle test” (with vehicle diagnosis system – checking faults)
And:		
61 21 528	Refer to KSD2	Connect an approved battery charger/power supply
(indicated in KSD2 as Charging battery)		
And		
17 99 000	4 FRU	Checking the function of the thermostat in the transmission heat exchanger
And:		
11 53 500	Refer to KSD2	Replacing coolant thermostat

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead.

And, as needed:

Sublet – Bulk Materials

Sublet Code 4	See sublet reimbursement calculation below	Reimbursement for replacing the drained quantity of antifreeze/coolant (bulk container reference BMW P/N 82 14 1 467 704, one gallon container. Please do not use this part number for claim submission.)
---------------	--	---

Sublet calculation: BMW antifreeze/coolant (1 gallon bulk container reference P/N 82 14 1 467 704) for approximately 1 liter that is needed for this repair (50/50 mixture) at dealer net plus handling.

Enter this material cost in sublet and itemize the amount in the claim comment section.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowance.

Labor operation code 17 99 000 is not considered a Main labor operation. Also, since the “work

time” FRU allowance to be claimed is specified, a separate punch time is not required

[Copyright ©2016 BMW of North America, Inc.]