



This Service Information bulletin supersedes SI M01 05 11 **dated October 2013**.

Please read this Service Information bulletin in its entirety: the content and format has been completely updated.

SUBJECT

N12 Tank Leak Diagnostic Module (DMTL) Pump: Limited Warranty Extension to 10 Years/120,000 Miles

MODEL

R55 (Cooper Clubman)

Model Years 2008 and 2009 produced from 7/25/2007 to 8/29/2009

R56 (Cooper Hardtop)

Model Years 2007, 2008 and 2009 produced from 11/22/2006 to 8/29/2009

R57 (Cooper Convertible)

Model Year 2009 produced from 10/15/2008 to 8/29/2009

With the N12 engine

INFORMATION

NEW This updated version of this bulletin now includes the addition of the model year 2009 R55, R56 and R57 MINI Cooper vehicles with the N12 engine.

For the above-referenced vehicles, MINI USA, a division of BMW of North America, LLC (“MINI USA”) is extending the limited warranty for the Tank Leak Diagnostic Module (DMTL) Pump to:

- 10 years/120,000 miles as determined by the vehicle’s original in-service date

Component #1: This “component-specific” limited warranty extension applies to defects in materials and workmanship and is subject to the applicable vehicle and coverage eligibility requirements, exclusions and limitations that apply to the MINI New Passenger Car Limited Warranty.



GRUSB0116-04

This bulletin is notice of a “limited warranty extension.” This is NOT a notice of a Recall or Service Action.

There is no immediate repair required unless the MINI vehicle is currently experiencing this problem.

Even though this is **NOT** a Recall, MINI USA will be sending VIN-specific customer notification letters in a phased release.

Customer Notification Letter – VIN and Component-specific Warranty Extension

Even though this is **NOT** a Recall, MINI USA will be sending VIN-specific customer notification letters in a phased release for the additional MY 2009 vehicles.

ELIGIBLE MINI VEHICLES

To assist you in identifying the eligible vehicles, the DCSnet Warranty Vehicle Inquiry has been updated with the “Vehicle Comment” shown below:

MY 2007 and 2008

MINI has extended the warranty of the Fuel Tank Leak Diagnostic Module (DMTL) from 4 years or 50,000 miles to 10 years or 120,000 miles, whichever occurs first. Details are contained in SI M01 05 11.

MY 2009

MINI USA, a division of BMW of North America, LLC has extended this vehicle’s Tank Leak Diagnostic Module (DMTL) Pump limited warranty to 10 years or 120,000 miles as determined from the original in-service date. This component-specific limited warranty extension is subject to all the applicable vehicle and coverage eligibility

requirements, exclusions and limitations that apply to the MINI New Passenger Vehicle Limited Warranty. Please see SI M01 05 11 dated March 2016.

Note: Always check the DCSnet Warranty Vehicle Inquiry “Vehicle Comments” and the “Repair History (Claims)” sections first before performing any repairs.

PROCEDURE

When diagnosed, one or more of the following “DMTL diagnosis module tank leakage, system failure” fault codes are stored in the DME:

- 2733 DMTL, module error
- 2734 DMTL, module error
- 2735 DMTL, module error
- 2736 DMTL, module error

If one of the vehicles above has the listed fault(s) stored in the DME, for this specific repair procedure only, please **do not** perform the corresponding test plan. Replace the DMTL pump with the improved version.

For the DMTL pump replacement instructions, refer to REP 16 13 015.

If any other faults are stored, perform the applicable test plans.

PARTS INFORMATION

Please refer to the Electronic Parts Catalog (ETK/EPC), using the customer’s VIN to locate the applicable replacement part number(s).

Important Notes:

- **Only order these parts in the quantities needed to address customers’ vehicles that have confirmed failures.**
- Also refer to ETK/EPC and the repair instructions for onetime-use fasteners/screws and other information regarding repair-related gaskets, seals, fluid and/or lubricants that also need to be replaced/used and claimed.

Part Number	Description	Quantity
16 13 7 193 479	Leak diagnosis pump	1

Important Notes:

- **Only order these parts in the quantities needed to address customers’ vehicles that have confirmed failures.**
- Also refer to ETK/EPC and the repair instructions for onetime-use fasteners/screws and other information regarding repair-related gaskets, seals, fluid and/or lubricants that also need to be

replaced/used and claimed.

WARRANTY INFORMATION

The tank leak diagnostic module (DMTL) pump limited warranty extension to 10 years/120,000 miles applies to “eligible US-specification MINI vehicles” that are registered, operated and have their covered repair performed by an authorized MINI dealer in the United States (including Puerto Rico).

This coverage supersedes the coverage that is provided under the MINI NEXT Certified Pre-Owned Program or any BMW Group Vehicle Service Contract that applies to the vehicle.

Should the DMTL pump fail again, this component is covered by the remaining portion of the extended limited warranty coverage period.

The existing limited warranty coverage for all other parts **has not** changed.

Non-Qualifying Repairs

Non-US specification vehicles, ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico and/or the diagnosis and repair of other unrelated issues are not covered under the terms of this limited warranty extension.

Qualifying Repairs - Claim Submission

Claim this work with the defect code and labor operations provided below.

Defect Code:	16 13 90 22 00	
Labor Operation:	Labor Allowance:	Description:
00 60 009	Refer to KSD2	Run a vehicle test and replace the DMTL Pump (Main work)
Or:		
00 60 543	Refer to KSD2	Run a vehicle test and replace the DMTL Pump (Plus work – Vehicle already in the workshop)

If you are using a Main labor code for another repair, use the Plus code labor operation 00 60 543 instead.

Refer to KSD2 for the corresponding flat rate unit (FRU) allowance.

MY 2009 MINI Vehicles: Previous Customer-pay Repairs – Limited Warranty Extension Reimbursement

Under this extended limited warranty, MINI USA, a division BMW of North America, LLC

(“MINI USA ”) will provide reimbursement for “qualifying customer-pay repairs” that were performed on an eligible model year 2009 vehicle prior to the release of this component-specific limited warranty extension.

Repairs that do not Qualify for Reimbursement

Repairs performed on ineligible vehicles, eligible vehicles operated and repaired outside the United States and Puerto Rico and/or the diagnosis and repair of other unrelated issues. This exclusion also applies to repairs, including consequential, that were performed using non-genuine MINI parts and/or used passenger car parts.

Customer-pay Invoice Review and Reimbursement Procedure

1. Review and verify that the previous customer-pay invoice (MINI dealer or independent repair shop) contains a qualifying repair to replace the component that is identified in this Service Information bulletin.
2. If this prior repair qualifies, reimburse the customer (labor and parts).
3. Submit for this customer-paid repair expense under **Defect Code 85 10 03 03 NA**, as follows:
 - o Sublet Code 3
 - o Dollar amount (with no markup)
 - o Comment: DMTL Pump: Limited Warranty Extension - Reimbursement for allowable expenses that relate to performing a qualifying prior customer-pay repair.
 - o Itemize the sublet amount on the repair order and in the claim comments
4. Retain the “original” customer pay invoice in your files; this documentation may be requested by MINI during the claim review process.

ATTACHMENTS

View PDF attachment [**M010511 Customer Letter A.**](#)

View PDF attachment [**M010511 MINI Customer Letter B.**](#)

[Copyright ©2016 BMW of North America, Inc.]