



SI B51 15 16
Body Equipment

May 2016
Technical Service

Delivery Stop – Check/Replace Windshield Sealing

MODEL

F06 (6 Series Gran Coupe)	F13 (6 Series Coupe, incl.M6)
---------------------------	-------------------------------

SITUATION

A Delivery Stop has been issued on the F06 and F13 vehicles produced from April 6, 2016 to April 8, 2016. These vehicles will require a check/replace of the windshield for possible water leaks. There are only nine vehicles affected by this stop. For your convenience, attached you will find the list of affected chassis#.

This bulletin will be updated with repair instructions and warranty information when they become available.

Affected vehicles can be identified with a “Vehicle Comment” in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

“A Delivery Stop has been issued for this vehicle. Dealers must ensure that all Campaigns are completed before retail delivery to the customer. Refer to Service Information Bulletin B51 15 16.”

ATTACHMENTS

View PDF attachment [B511516 Delivery Stop Legal.](#)

View PDF attachment [B511516 VINs.](#)

[Copyright ©2016 BMW of North America, Inc.]