

<b>Subject</b> <b>16-17MY Sequoia Vibration at Highway Speeds</b>		<b>Market</b> <b>USA</b>
<b>Service Category</b> <b>Suspension</b>	<b>Section</b> <b>Tire/Wheel</b>	
<b>Applicability</b> <b>16-17MY Sequoia</b>		

**APPLICABLE VEHICLES**

2016-2017

Sequoia

**CONDITION**

Some 16-17MY Sequoia vehicles with Original Equipment (O.E.) wheels and tires, and less than 15,000 miles may experience a vibration concern when driving at highway speeds. Seeking vehicles with no previous repair attempts for investigation.

**RECOMMENDATIONS**

This issue is currently under investigation. Please create a TAS case and contact Technical Assistance (TAS) to submit details on any vehicle identified matching the condition described in this document prior to repair.

If you are attempting to contact TAS on a weekend or TMS holiday, continue with diagnosis and submit the requested information on the next available work day. Retain all replaced parts and technician notes for possible review with TMS TAS Product Engineer.

**LINK REFERENCES**

This Tech Tip does not contain any link references