



SERVICE BULLETIN

Classification: HA16-003	Reference: NTB16-033	Date: March 28, 2016
-----------------------------	-------------------------	-------------------------

2014-2016 ROGUE; HVAC CONTROLLER SERVICE INFORMATION

APPLIED VEHICLES: 2014-2016 Rogue (T32)

NOTE: This bulletin does not apply to the Rogue Select (S35)

SERVICE INFORMATION

If the HVAC system control unit is replaced for any reason:

- After replacement, make sure to perform **Door Motor Starting Position Reset** using CONSULT-III plus (see Figure 1).
- This function is found in **HVAC > Work support**.




Figure 1

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.