



Parts Bulletin

TITLE:

Recall R89708: Front Passenger Seatbelt Buckle; Model Year 2016-2017 XC90, S90, XC60, V60CC, V60, S60, S60CC, S60 Inscription

GROUP: 88	CAT/NO: R89708	REFERENCE BULLETINS: QB: R89708, TJ: 32058	CAR MARKET: United States and Canada	
COPY TO / CIRCULATIONS (PLEASE INITIAL):			ISSUE DATE: 2016-11-02	STATUS DATE: 2016-11-02
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	
				Page 1 of 2

“Right first time in Time”

Reference Bulletins: QB: R89708, TJ: 32058

Volvo Car USA LLC and Volvo Car Canada LTD (Volvo) on behalf of Volvo Car Group has decided to launch Recall R89708 on certain model year 2016 - 2017 XC90, S90, XC60, V60CC, V60, S60, S60CC, S60 Inscription vehicles.

The affected vehicles may have not had the front passenger seatbelt buckle stud punched correctly. This may result in a separation between the buckle and the seat belt bracket. If this were to occur, it could increase the risk of injury to a front passenger seat occupant in a vehicle crash.

Authorized Volvo retailers will inspect the front passenger seatbelt buckle stud by pushing/rotating the passenger seatbelt buckle forward, and checking if the seatbelt buckle stud is punched according to the illustrations in TJ32058.

If the inspection procedure indicates an incorrectly manufactured seatbelt buckle, Volvo retailers will replace the seatbelt buckle.

A total of 74,027 U.S. and 5,084 Canadian vehicles are eligible for this recall.

Parts Bulletin 88-R89708



The following part numbers apply:

Part Number	Description	Qty
31369302	Seatbelt Buckle (XC90, S90)	1
31436951	Seatbelt Buckle (Model 60 Cars)	1
983750	Cable Tie (Model 60 Cars)	4

The predicted percentage of vehicles that require the seatbelt buckle replacement is very low. Parts availability is currently limited. As a result, the seatbelt buckles are restricted to critical orders only. Continue to check VRC² Parts Announcements for order procedure and availability updates. Please order only what is required to repair a vehicle with a confirmed incorrectly manufactured seatbelt buckle per TJ 32058.