



Search...

Search

Marie-Claude Simard

Help & Training

Call Center

[Home](#) [Accounts](#) [Cases](#) [Contacts](#) [Reports](#) [Dashboards](#) [Chatter](#) [Community](#) [Articles](#) [Files](#) [RPQ Buckets](#) [BOSSWeb Logout](#)[Reply](#) [Topic Options](#)[Message Listing](#)[Previous Topic](#)[Next Topic](#)**DanyD**

BRP Technical Hub - Global

Posts: 1,158
Registered: 10-19-2011
Location: NA**✓ 2016 F3-T & LTD issue with B.U.D.S. R3.7.0** [Edited][Options](#)

2 weeks ago - last edited 2 weeks ago

Everyone, please be aware that we have a situation with B.U.D.S. R3.7.0 (current version) and 2016 F3-T & LTD units. Seems the 2016 F3-T & LTD **VCMS** are not being read correctly with the current B.U.D.S. version. You may encounter variant coding codes, DPS updates and other various issues still being discovered.

At this time, VCMs service parts have been blocked to avoid unnecessary replacement as the issue is not with the VCM itself but how B.U.D.S. is reading it.

Eng and PPQ are working with BUDS dev. to correct the situation by the end of this week (Feb 27th, 2016) with the release of B.U.D.S. E3.7.2.

If you have a similar situation, open a BOSSWeb Technical Case for immediate support.

DO NOT CHANGE THIS SETTING - this is what starts the whole mess up.

B.U.D.S. R3.7.0 does not recognize the F3-T and LTD model as a choice but on the vehicle side it is correct.

Setting/Vehicle Configuration

Vehicle Configuration

Vehicle	SPYDER
Platform	uninitialized
Engine	1330 ACE
Variant	SE
Country Options	CU
Model Year	MY16