



AUTOMOBILE DIVISION

American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

VEHICLE IDENTIFICATION NUMBER: XXXXXXXXXXXXXXXXXXXX

PLEASE DELIVER TO REGISTERED OWNER



JW4

T25 **AUTOMIXED AADC 296 PL1 R

D1-0008819



▼ PLEASE DETACH, SIGN BELOW AND PLACE IN RETURN ENVELOPE ▼

INFORMATION CHANGE CARD

PLEASE PROVIDE NAME AND ADDRESS CORRECTIONS ON THE REVERSE SIDE

XXXXXXXXXXXXXXXXXXXX

◀ VEHICLE IDENTIFICATION NUMBER

JW4



PLEASE SIGN AND RETURN THIS CARD ONLY IF YOU HAVE MADE CHANGES

AHA001 0008819

I no longer own this vehicle. It was:

- Sold (*print name and address of new owner on reverse, if known*)
- Exported
- Destroyed
- Stolen
- Lease expired, vehicle returned.
- Other:

Nota:

Si usted necesita esta información en español por favor comuníquese con Servicio al Cliente de Automóviles Honda al 1-888-234-2138.

Signature: **X**

Date: _____

SIGNATURE OF REGISTERED OWNER OR LESSEE REQUIRED



AUTOMOBILE DIVISION

American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

February 2016

Product Update: 2016 HR-V Door Handle Bracket

VIN: XXXXXXXXXXXXXXXXXXXX

Dear _____ :

A non-galvanized door handle bracket located inside the front passenger's door was installed during manufacturing and may be susceptible to corrosion.

What should you do?

Call any authorized Honda dealer and make an appointment to have your vehicle repaired. The dealer will replace the front passenger's door handle bracket and remove any corrosion found from the door handle area. The repair takes about 90 minutes; however, your vehicle may need to be at the dealer for a longer period of time. We recommend that you plan to leave your vehicle for half a day to allow the dealer flexibility in scheduling. In rare cases of significant corrosion, further repairs may be needed and may take several days. This work will be done free of charge.

Lessor Information

Please forward a copy of this notice to the lessee.

What to do if you feel this notice is in error

Our records show that you are the current owner or lessee of a 2016 HR-V involved in this product update. If this is not the case, or the name/address information is not correct, please fill out and return the enclosed postage-paid Information Change Card. We will then update our records.

If you have questions

If you have any questions about this notice, or need assistance with locating a Honda dealer, please call Honda Automobile Customer Service at 1-888-234-2138. You can also locate a dealer online at www.hondacars.com. Customers in U.S. territories, please contact your local distributor/dealer.

Sincerely,

American Honda Motor Co., Inc.
Honda Automobile Division

Febrero del 2016

Actualización de producto: Soporte de la manija de la puerta del HR-V 2016

VIN: XXXXXXXXXXXXXXXXXXXX

Dear _____ :

Un soporte de la manija de la puerta sin galvanizar ubicado dentro de la puerta del lado del pasajero delantero fue instalado durante la fabricación y puede que este susceptible a la corrosión.

¿Qué debe hacer?

Llame a cualquier concesionario autorizado Honda y haga una cita para la reparación de su vehículo. El concesionario reemplazará el soporte de la manija de la puerta del lado del pasajero delantero y retirará cualquier corrosión que se encuentre en el área de la manija de la puerta. La reparación toma aproximadamente 90 minutos, sin embargo, su vehículo puede que necesite estar en el concesionario por un período prolongado de tiempo. Nosotros recomendamos que planifique dejar su vehículo en el concesionario por medio día para permitir algo de flexibilidad en la programación. En raros casos de corrosión significativa, podrían ser necesarias reparaciones más extensivas y podría tomar varios días. Este trabajo se realizará sin costo alguno.

Información para el arrendador

Por favor envíe una copia de esta notificación al arrendador.

Qué debe hacer si considera que esta notificación es errónea

Nuestros registros muestran que usted es el propietario o arrendador actual de un vehículo HR-V 2016 el cual forma parte de esta actualización de producto. Si no es el caso, o si la información de nombre/dirección no está correcta, por favor llene y devuelva la Tarjeta de Cambio de Información anexa con el porte pagado. Con esto actualizaremos nuestros registros.

Si tiene preguntas

Si tiene preguntas acerca de ésta notificación o si necesita asistencia para ponerse en contacto con un concesionario Honda, por favor comuníquese con Atención al Cliente de Automóviles Honda al 1-888-234-2138. Usted también puede ubicar un concesionario en línea en www.Hondacars.com. Los clientes en territorios de Estados Unidos, por favor comuníquese con su concesionario/distribuidor local.

Atentamente,

American Honda Motor Co., Inc.
División automotriz de Honda



AUTOMOBILE DIVISION

American Honda Motor Co., Inc.

P.O. Box 4713

Trenton, NJ 08650

PRESORTED
FIRST-CLASS MAIL
U.S. POSTAGE PAID
American Honda
Motor Co., Inc.

FIRST-CLASS MAIL

PRODUCT ADVISORY

PLEASE OPEN IMMEDIATELY

IMPORTANT: PRODUCT ADVISORY ENCLOSED



© 2000 Honda Motor Co., Ltd. All rights reserved.