

2/17/16

MY15, 16

RT

GPOP - Issue Review System

Part Number: 68257920A\$

Part Description: WIN Module

Issue Description: Prior to replacing the WIN module on RT vehicles only for no start 'Bad Key Message' or key cannot be removed while the vehicle is in park, verify the WIN Module connector is fully inserted.~
The connector locking tab feature should not allow a release from the WIN Module mating port without depressing the locking tab feature on the harness side of the connector.~

~Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.