

2/17/16

MY16 UF

## **GPOP - Issue Review System**

**Part Number:** 68271006A\$

**Part Description:** Center Console USB Hubs

### **Issue**

**Description:** Before replacing the USB hub on 16UF for intermittent issues, contact Dave Diovardi at (cell) 248-941-8704. Engineering is currently root causing this issue. If no response is received within 15 minutes, then please proceed with repair.

~Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.