

2/26/16

MY14, 15

KL

GPOP - Issue Review System

Part Number: 68317470A\$, 68317471A\$, 68317472A\$, 68317473A\$, 68314481A\$, 68314482A\$, 68314483A\$, 68314486A\$, 68314487A\$, RL317470A\$, RL317471A\$, RL317472A\$, RL317473A\$, RL314481A\$, RL314482A\$, RL314483A\$, RL314486A\$, RL314487A\$, R8317470A\$, R8317471A\$, R8317472A\$, R8317473A\$, R8314481A\$, R8314482A\$, R8134483A\$, R8134486A\$, R8134487A\$

Part Description: 9-Speed Transaxle

Issue Description: This 9-speed transaxle must be ordered thru Mopar's VIN Order Entry system for a specific VIN and must be installed in that vehicle or the correct calibration will not load to the Engine Control Module (ECM) and Transmission Control Module (TCM).~

~
This 9-speed transaxle assembly requires an update to the Engine Control Module AND the Transmission Control Module using WiTech. Failure to complete both updates will result in possible damage and/or incorrect operation of this unit.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
