

9/28/2016 15, 16 PF, KL, UF

GPOP - Issue Review System

Part Number: 68245074A\$, 68255593A\$, 68255595A\$, 68247204A\$, 04787708A\$, 68285225A\$, 68103256A\$, 68213158A\$, 68194991A\$, 68103259A\$, 68213159A\$, 68081634A\$, 68193946A\$, 68193947A\$, 68258663A\$, 55111484A\$, 68103140A\$, 68103137A\$, 68194889A\$, 68195662A\$

Part Description: Compressor, A/C lines, A/C Condenser

Issue This issue pertains to PF, UF, and KL only.~

Description: During service of the AC lines, Compressor or Condenser, do not stow any AC lines in proximity to any heat sources, or sharp edges.~

After the vehicle is reassembled, confirm that all AC lines are in correct design position and not in contact with any heat sources, or sharp edges.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
