

4/20/2016 MY15 & 16 WD, WK

GPOP - Issue Review System

Part Number: 68240156A\$, 68240157A\$, 68211124A\$, 68211125A\$

Part Description: Radio Frequency Module RF_HUB

Issue Description: Before Replacing RFHM (RF-hub) for any reason for 2015 or 2016 WD or WK ONLY; Call RFHM release engineer Majdi Yaqub at cell (248) 763-5747. If no response within 15 minutes, proceed with repair.~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.