

5/11/2016 MY 14, 15, 16 KL, UF

GPOP - Issue Review System

Part Number: 68175510A\$, 68175511A\$, 05090044A\$, 05090045A\$, 68155227A\$, 68155228A\$

Part Description: Rear trailing arm/link.

Issue Customer noise issue due to loose trailing link

Description: If a trailing link is damaged or noisy, please call Steve Lin at Cell 909-569-5117 prior to removing the part. If you do not hear from us within 15 minutes please continue with the repair.

~ ~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.