

8/10/2016 MY12, 13, 14, 15 DS

GPOP - Issue Review System

Part Number: 68157611A\$, 68157610A\$

Part Description: Caliper Assembly - Front Disc Brake

Issue For an issue with drift only while braking, do not replace front Caliper Assemblies.
Description: Check the front brake pads for contamination, replace if necessary, and clean the friction surfaces of both front rotors. If that doesn't resolve issue, check vehicle alignment. ~

~
~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.