 15805 - Service Update for Inventory Vehicles Only - Transmission Oil Cooler Line Disconnect
Updated Date: Jan 27, 2016 9:40 ET

GM CUSTOMER CARE AND AFTERSALES
DCS3907
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 27, 2016

Subject: 15805 – Service Update Bulletin for Inventory Vehicles Only
Transmission Oil Cooler Line Disconnect

Models: 2015 – 2016 Chevrolet Colorado
2015 – 2016 GMC Canyon
Equipped with 2.5L or 3.6L Engine (RPO LCV or LFX)

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator


General Motors is releasing Service Update Bulletin 15805 today. The total number of U.S. vehicles involved is 24,454. Please see the attached bulletin for details.


Global Warranty Management (GWM)

The "Investigate Vehicle History" (IVH) screen will be updated later this week. A list of involved vehicles in dealer inventory is attached to this message.

Please hold all warranty claims until the VINs are loaded into IVH.

GM CUSTOMER CARE AND AFTERSALES

 15805 Bulletin.pdf

 15805 US Stock list.xlsx

About this Alert

Reference Number: GCUS-3-416

Published to: Home Page

Version: 1.0

Alert Type: Service Update

Original Published Date: Jan 27, 2016 9:40 ET

Expires: Mar 27, 2016 0:00 ET

Contact : loren.rusk@gm.com