



SERVICE BULLETIN

Classification:

EC14-010a

Reference:

NTB15-026a

Date:

April 14, 2016

2014-2015 ROGUE; LACKS POWER DUE TO SNOW INGESTION

<p>This bulletin has been amended. Installation of hood foam has been added to the Service Procedure. Please discard previous versions of this bulletin.</p>

APPLIED VEHICLE: 2014 - 2015 Rogue (T32)

APPLIED VIN & DATE: See Repair Flow Chart on page 2 for VIN and Date information.

IF YOU CONFIRM:

An applied vehicle experiences reduced power during extremely heavy snow fall

And

Snow is found inside the air cleaner case.

NOTE: The MIL may be ON with DTC P0101 (MAF SEN/CIRCUIT B1) stored.


ACTION:

See Repair Flow Chart on page 2 to confirm that this bulletin applies.

IMPORTANT: The purpose of ACTION (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire SERVICE PROCEDURE as it contains information that is essential to successfully completing this repair.

<p>Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.</p>

REPAIR FLOW CHART



SERVICE PROCEDURE

1. Has Op-Code **BX4NAA** or **BX4PAA** been performed previously on this vehicle (refer to Service COMM for previous warranty claims)?

YES: Perform Service Procedure steps 2 - 7 ONLY.

NOTE: If Op-Code BX4NAA or BX4PAA was previously performed, step 8 and 9 were already done and do not need to be done again.

NO: Perform Service Procedure steps 2 – 9.

2. Open the engine hood.
3. Remove any snow from inside the air duct assembly, resonator, and air cleaner case.
4. Replace the air cleaner filter.
5. Clean the area of the hood with 50% isopropyl alcohol where the hood foam block will be attached (shown highlighted in Figure 1).
6. Install the hood foam block (Figure 1).
 - Hood foam block is listed in the Parts Information.




Figure 1

7. If stored, erase DTC P0101.

STOP: Continue with the Service Procedure only if **BX4NAA** or **BX4PAA** have not been previously performed on this vehicle.

8. Remove the front grill, and then remove the foam near the driver side (left side) headlamp (see Figure 2).
- Refer to the Electronic Service Manual (ESM), section **EXT - Exterior**, for front grille removal information.





Figure 2

9. Replace the front grille with the new one listed in the Parts Information.
- If there is a front camera, transfer it from the old grille to the new grille.
 - Refer to the ESM, section **EXT - Exterior**, for front grille installation.
 - If the new grill has a front camera, refer to the ESM, section **AV - Audio, Visual & Navigation System**, for front camera image calibration.



Front grilles: Facing down, viewed from underneath

Figure 3




Figure 4

PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
GRILLE ASSY – FRONT Without front camera	62310-9TA0A	1
GRILLE ASSY – FRONT With front camera	62310-9TA0B	
Hood Foam Block	65813-4BA0A	1
Air Cleaner Filter	16546-4BA1A	1

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
RPL Front Grille with Navi	(1)	BX5UAA	ZE	32	0.8
RPL Air Cleaner Filter		TB26AA			(2)

(1) Refer to the **PARTS INFORMATION** table and use the applicable front grille assembly.

(2) Refer to the Nissan Online Warranty Flat Rate Manual for the flat rate time

OR

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
RPL Front Grille without Navi	(1)	BX5TAA	ZE	32	0.3
RPL Air Cleaner Filter		TB26AA			(2)

(1) Refer to the **PARTS INFORMATION** table and use the applicable front grille assembly.

(2) Refer to the Nissan Online Warranty Flat Rate Manual for the flat rate time

OR

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Install Hood Foam, and Clear DTC	65813-4BA0A	BX5SAA	ZE	32	0.3
RPL Air Cleaner Filter		TB26AA			(2)

(2) Refer to the Nissan Online Warranty Flat Rate Manual for the flat rate time