

6/29/2016 MY15 LA, LD, LX

GPOP - Issue Review System

Part Number: 68239269A\$, 68230108A\$

Part Description: Exhaust Actuator and Valve Spring

Issue Description: - If an electronic exhaust valve spring is broken, please replace the spring with PN 68319331AA~
- If spring is not broken and replacing actuator, please contact Jason Maltese Cell (248) 931-4179 - exhaust engineer. ~
If no response in 15 minutes, proceed with repair~
~

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
