



Ferrari North America

Technical Information

Date:	July 2016
Bulletin #:	2356
Campaign #:	
Supersedes:	
Section:	10

Model Type: 488 GTB, 488 Spider
Model Year: All
Subject: Updated PDI procedures

This Technical Information is an **UPDATE** to the previous TI **2266** for the **488 GTB**.

This Technical Information is an **UPDATE** to the previous TI **2308** for the **488 Spider**.

Please note that it is necessary to amend the PDI procedures for the aforementioned vehicle, including the operation for **checking that the screws fastening the rear element of the flat undertray are tightened correctly**. This operation, which must be performed after refitting and fastening the rear undertray element to the chassis, will be part of the PDI procedure until further notice.

Thank you for your co-operation.