

Service Bulletin

PRELIMINARY INFORMATION

Subject: Turbocharger Part Restriction

Models: 2016 Cadillac ATS-V Equipped with a 3.6L LF4 Twin Turbocharged Engine

This PI was Superseded to update parts information. Please discard PIP5372.

Condition/Concern

General Motors, as part of our continued quality and improvement objective has decided to issue a part restriction through GM Technical Assistance on the turbochargers for the ATS-V LF4 engine.

Recommendation/Instructions

If during your diagnosis, you find there is a concern with the turbocharger on this vehicle that requires replacement, you will be required to call Technical Assistance (TAC) to order the part.

Prior to calling TAC please reference the latest version of PI1234 which describes a normal noise condition of this vacuum operated turbocharger wastegate. Also there are sound files available in the January 29, 2016 issue of tech link describing normal turbocharger rattle.

Prior to calling TAC if the concern with the turbocharger is a noise you will need to obtain a sound file or video of the noise and send it in to TACSNAPSHOT@gm.com

Parts Information

| Part Number | Part Description | |
|------------------------|----------------------------------|--|
| 12666536 | Right (B1) Turbocharger Assembly | |
| (until stock depleted) | | |
| Then FSU | | |
| 12673347 | | |
| 12666537 | Left (B2) Turbocharger Assembly | |
| (until stock depleted) | | |
| Then FSU | | |
| 12673348 | | |

Warranty Information

For vehicles repaired under warranty use:

| Labor Operation | Description | Labor Time |
|-----------------|----------------------|--------------------------|
| 4068290 | Turbocharger Replace | Use Published Labor Time |

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION