



Date: Aug-2016

# Service Bulletin

# PRELIMINARY INFORMATION

Subject: GM Accessory Fender Flares Loose

Models: 2015-2016 Chevrolet Colorado

This PI was superseded to update Parts and Warranty Information. Please discard PIT5478.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

#### Condition/Concern

The customer may state the accessory fender flares are pulling away from the fender and/or appear loose.

#### Recommendation/Instructions

It is recommended to review the 2015 Oct Emerging Issues Video before performing the procedure below.

US Dealers should access the video as follows:

- https://www.centerlearning.com
- Log in
- · Select the "Catalog" icon at top
- Change "Course Name" to "Course Numbers"
- Enter "10215.10D" in the Search box
- Select "View"
- Select "Take or Continue Course" near the top right

The "2015 Colorado, Canyon Fender Flares" video is approximately 6 minutes long and starts approximately 28:45 minutes into the emerging issues video. The video scroll bar can be pulled across to the 28:45 minute mark and start watching the video from that point. Note: You may not be able to fast forward the video until it is fully loaded.

Canada Dealers should access the GM Centre of Learning website, then follow this path:

- Resources
- Video on Demand
- GM Pro Centre of Learning
- Service Technical
- PIT5478

### **Parts Information**

| Part Number | Description     | Qty |
|-------------|-----------------|-----|
| 23288130    | LF Fender Flare | 1   |

| 23288131 | RF Fender Flare | 1 |
|----------|-----------------|---|
| 84059965 | LR Fender Flare | 1 |
| 84059966 | RR Fender Flare | 1 |

## **Warranty Information**

For vehicles repaired under warranty use:

| Labor Operation  | Description                                | Labor Time |  |  |
|--|--|------------|--|--|
| * 0580168  | Remove and Install Accessory Fender Flares | .4 hr each |  |  |
| * This is a unique labor operation for bulletin use only |  |            |  |  |

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

