

SERVICE ALERT

[Print](#)

Date: 2016-08-25

[Close](#)Service Alert
No: SA-001308Subject: 2014-16 MAZDA3 (WITH MANUAL A/C) - AIR TEMPERATURE WILL
NOT CHANGE

If you encounter a Mazda3 where the air temperature of the climate control will not change, perform [TSB 07-003/15](#) only if the vehicle is within in the VIN range specified. Vehicles outside the VIN range already have the modified temperature control link misted in the TSB.

NOTE: If the exact same concern exist on a vehicle outside the VIN range or on a vehicle within the VIN range where TSB 07-003/15 has been performed once already, call Hotline for further assistance. Otherwise, follow normal troubleshooting procedures according to MS3 online instructions.