



# Service Bulletin

## INFORMATION

**Subject:** Elimination of Rear Seat Floor Filler Trim Panel as Standard Equipment

**Models:** 2014-2017 Chevrolet Equinox  
2014-2017 GMC Terrain

**Attention:** This PI also applies to any of the above models that may be North America Export to Middle East and Israel vehicles.

*This PI has been revised to add the 2017 Model Year. Please discard PI1023C.*

### Condition/Concern

Some customers may comment that their vehicle is missing the rear seat floor filler trim panel.



As shown in the graphic above, in previous model years 2010-2013, these vehicles included the rear seat floor filler trim panel as standard equipment.



Starting with 2014 vehicle production, the floor filler trim panel was eliminated as standard equipment. The seat/floor interface will now look like the example shown in the graphic above.

### **Recommendation/Instructions**

No repairs are necessary and please advise the vehicle owner of the standard equipment change.

**Note:** The installation and cost of adding the floor filler panel will not be covered under the vehicle's warranty and would be at the customers expense.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION