

SSM 45988	Some 2015-2016 Fiesta with 1.6L TiVCT engine may have a check engine light with DTC's P0351 and/or P0352 with possible runs rough, hard or no start. Follow PPT JE for normal diagnostics. If light flash is inconsistent or dim in step JE4; suspect a damaged or warped hall effect window on the engine flywheel. Replace the flywheel using Workshop manual section 303-01. Use applicable labor operations from Section 6 of the SLTS Manual. If light is consistent continue to follow normal diagnostics.
--------------	--