

SSM 46013	Some 2014-2015 Focus and Fiesta vehicles equipped with a 1.0L GTDI built on or before 07/25/2015 may exhibit lack of power and multiple miss fire diagnostic trouble codes (DTC). If normal engine diagnosis leads to low compression and piston damage, inspect the exhaust valves for a pin hole in the center of the valve head.
--------------	---