

# Technical Service Bulletin



## 57 Anti-theft alarm goes off without cause

57 16 29 2045051/1 August 15, 2016.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4	2017	All	Not Applicable
Q7	2017	All	Not Applicable

## Condition

- The anti-theft alarm goes off without a cause.
- **DTC B131DF6** (Sirens/alarm horn for anti-theft warning system wrong code) is stored in the comfort system central control module, J393 (address word 46).

## Technical Background

The software of the comfort system central control module, J393 (address word 46) needs to be updated. The updated software will resolve the false alarm.

## Production Solution

Optimized software.

## Service

### SVM Update Instructions

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the comfort system central control module, J393 (address word 46), using the SVM action code as listed in the table below, if necessary.  
On the ODIS tester, enter the SVM code in operation mode "update".

Model	Old Software Part Number	Old Software Version	New Software Part Number	New Software Version (or higher)	SVM Code Input
A4	4M0907064*	<0329	4M0907064*	0329	46A016
Q7	8W0907064*	<0329	8W0907064*	0329	

# Technical Service Bulletin



## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"><li>• 110 up to 48/50</li><li>• G10 for CPO covered vehicles – verify owner</li><li>• If vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li></ul>		
<b>Service Number:</b>	5789		
<b>Damage Code:</b>	0039		
<b>Diagnostic Time:</b>	GFF	0150 0000	Time stated on diagnostic protocol (Max 70 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
	Technical diagnosis at dealer's discretion (Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)		
<b>Claim Comment:</b>	As per TSB #2045051/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All parts and service references provided in this TSB (2045051) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.