



Title

2010-13 MAZDA3 - HAZARD WARNING LIGHTS STAY ON AFTER DASH REPAIR

Content

If you encounter the hazard warning lights staying on after a dash repair, you may have crossed the hazard warning switch connector with another connector, such as the Bluetooth microphone connector. The two connectors have the same number of pins.

0920-403
MICROPHONE



0918-501
HAZARD WARNING SWITCH /
HAZARD WARNING SWITCH
ILLUMINATION /
CLOCK SWITCH

