
Reference	SSM72858
Models	XF / X260
Title	17 MY X260 rear plate plinth detached
Category	Body
Last modified	05-Jul-2016 00:00:00
Symptom	108000 Ext. Trim/Accessories
Attachments	Plinth fixings position.pdf (Plinth fixings position.pdf)

Content

Issue: USA Port of Entries have seen a recent spike in X260 rear plate plinths losing adhesion, and falling off the vehicle.

Cause: The root cause is still under investigation, however initial results are suggesting the adhesive tape is failing Plinth side and not body side.

Action: Please be aware as containment action from Castle Bromwich, number plate plinths will be secured into position with 2x mechanical fixings until further notice. See attachment for location of the fixings.

