
Reference	SSM72885
Models	F-PACE / X761 XE / X760 XF / X260
Title	DTC P025C-11 - Fuel Pump Module `A` Control Circuit Low - AJ126 Only
Category	Engine
Last modified	20-Jul-2016 00:00:00
Symptom	404000 Fuel System Concerns

Content **Issue:** MIL illuminated and with DTC P025C-11 for Fuel Pump Module "A" Control Circuit Low - Circuit short to ground

Cause: False flagging DTC P025C-11

Action: Upon investigation JLR and the supplier have concluded there is no fault with the (FPDM) fuel pump driver module component. **Please do not replace the module**, please clear the DTC using SDD and roadtest the vehicle and make sure the DTC does not return. If the DTC does return please raise a TA for further assistance.

A Technical Bulletin will be released shortly aligned with an SDD patch