

SSM 46233	<p>Some 2017 Escape vehicles equipped with 17 inch wheels built on or before 10-Oct-2016 may exhibit an electric park brake warning with diagnostic trouble codes (DTCs) C1034, C1A43, C2005, C2007, C2008 and/or U2002. 4 wheel drive (4WD) vehicles may also exhibit an Anti-lock Brake System (ABS) light on with DTCs C003A or C0037. If a vehicle comes in for this concern, inspect the electric park brake/brake skid control wiring harness (2C055) in the rear on both sides. Inspect the harnesses for damage where they are routed closest to the rear wheels. If damaged, repair as required and tie strap both harnesses to gain sufficient clearance away from both rear wheels. Applicable labor operations in section 10 of the service labor time standards (SLTS) manual.</p>
--------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------