
Reference	SSM72875
Models	F-PACE / X761 F-TYPE / X152 XE / X760 XJ / X351
Title	Homelink Universal Transmitter Programing
Category	Body
Last modified	01-Aug-2016 00:00:00
Symptom	112000 Latches/Locks & Security
Content	<p><u>Issue:</u> Homelink universal transmitter not working</p> <p><u>Cause:</u> Homelink universal transmitter not correctly programmed</p> <p><u>Action:</u> Updated instructions on how to programme the Homelink universal transmitter have been updated in TOPIx Section 501-09: Rear View Mirrors – Description and Operation - Rear View Mirrors This is now live in English with translations to follow shortly.</p>