

SSM  
46195

2017 Explorer and 2016 Taurus vehicles built on or after 9-Jun-2016 no longer have the fuel filler pipe information bezel attached to the fuel filler pipe. The bezel was removed to comply with fuel pump vapor recovery equipment requirements and should not be considered missing. The addition of the information bezel to units built on or after 9-Jun-2016 should not be done.