
Reference	SSM72962
Models	Discovery Sport / L550
Title	Discovery Sport 17 MY Tow Bar Fitment Configuration
Category	Electrical
Last modified	23-Sep-2016 00:00:00
Symptom	205000 Electrical Accessories
Content	<p><u>Issue:</u> The following message will be displayed - "Parking aid not available please consult your dealer", after a towbar has been fitted. Vehicle accessory fitting instructions already reflect the correct installtion methods.</p> <p><u>Cause:</u> The retailer has configured the new towbar using SDD.</p> <p><u>Action:</u> Discovery Sport vehicles from 17MY are pre-configured.</p> <ul style="list-style-type: none">• Do not configure the vehicles.• If you do configure, re-install the original CCF.