

Reference	SSM72918
Models	Range Rover / L405 Range Rover Sport / L494
Title	Noise From Front Brakes-High Performance Brakes
Category	Chassis
Last modified	08-Aug-2016 00:00:00
Symptom	301000 Service Brake System

Content **Model:**Range Rover (LG)
 Range Rover Sport (LW)

Issue:A customer may report a squeal from the front brakes during low speed braking.

Cause:This may be caused by front brake pad resonance.

Action: New brake pad parts are available in limited quantities to help address critical customer cases. An Electronic Product Quality Report (EPQR) with a sound file of the squeal must be submitted prior to the release of new parts. The EPQR number and VIN must be included in the customer material number field with all related parts orders for parts to be released to retailers.