

**** TECHNICAL INFORMATION NOTICE ****

DATE: December 6, 2016
TO: Mitsubishi Motors US & Puerto Rico Dealer Principals, General Managers, Service Managers, and Parts Managers
RE: Code 209 Restriction on ABS Hydraulic Unit Part Numbers
TIN NO. TIN-16-35-001

.....

AFFECTED VEHICLES: 2014 - 2016 Outlander Sport

PURPOSE

The ABS hydraulic unit parts for 2014 - 2016 Outlander Sport vehicles will be placed on 209 Restriction effective immediately.

Part Description	Part Number	Origin
ABS Hydraulic Unit	4670B183	MMNA
	4670B263	MMC

When diagnosing an ABS hydraulic unit exhibiting a brake fluid leak or seepage, please refer first to the Tech Talk article and TSB listed below before ordering a replacement ABS hydraulic unit:

- Tech Talk Volume 223, Group 35C, "Fluid Seepage at ABS Hydraulic Unit"
- TSB-16-35-001, "Hydraulic Unit Removal & Installation: Clamping Torque of Brake Tube Flare Nuts – SMR"

If the seepage/leak issue is still not resolved after following the diagnostics in the article and TSB listed above, have the Technician working on the vehicle create a Techline Case and call Techline (1-800-446-6064) prior to ordering an ABS hydraulic unit for a warranty repair.

Techline Support will discuss the condition on the customer's vehicle and if an ABS hydraulic unit replacement is required, they will have the part order released.