TECHNICAL BULLETIN LTB00989NAS1 31 MAY 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 501-08

'Sport' Badge Red Paint Delamination

AFFECTED VEHICLE RANGE:

Range Rover Sport (LW)

Model Year: 2014 Onwards VIN: 2014 Onwards

Assembly Plant: Solihull

MARKETS:

NAS

CONDITION SUMMARY:

Situation: The red infill paint on the tailgate 'SPORT' badge delaminate.

Cause: This may be caused by a paint adhesion issue.

Action: Should a customer express this concern, follow the Service Instruction outlined below to replace tailgate

'SPORT' badge.

PARTS:

| LR084216 | SPORT (Red) | 1 |
|----------|---------------------------|---|
| LR084212 | SPORT (Red) HSE SDV6 | 1 |
| LR084211 | SPORT (Red) HSE | 1 |
| LR084214 | SPORT (Red) SUPERCHARGED | 1 |
| LR084213 | SPORT (Red) AUTOBIOGRAPHY | 1 |
| LR084229 | SPORT (Red) HSE SCV6 | 1 |

TOOLS:

No Tools Required

WARRANTY:

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

| DESCRIPTION | SRO | TIME (HOURS) | CONDITION CODE | CAUSAL PART |
|------------------------|----------|--------------|----------------|-------------|
| Tailgate Badge - Renew | 76.44.04 | 0.2 | 70 | LR048879 |

NOTE: Normal Warranty procedures apply.

SERVICE INSTRUCTION:

1. CAUTION: Remove any excessive adhesive from the tailgate.

Using a suitable tool remove the tailgate badge.

- 2. Clean the area prior to installation of the new tailgate badge.
- 3. NOTE: The new tailgate SPORT badge is supplied on a cassette (highlighted in blue).
- NOTE: All dimensions shown are to the edge of the new badge cassette.

Using the dimensions shown, install the new tailgate SPORT badge.

