
| | |
|----------------------|--|
| Reference | SSM72887 |
| Models | Range Rover / L405 Range Rover Sport / L494 |
| Title | Range Rover (L405) & Range Rover Sport (L494) Hi-Line Rear Centre Armrest Cupholder |
| Category | Body |
| Last modified | 21-Jul-2016 00:00:00 |
| Symptom | 101000 Seating |
| Attachments | D7U Rear Armrest Silver Disc's.pdf (D7U Rear Armrest Silver Disc's.pdf) |

ContentIssue:

Range Rover or Range Rover Sport Customers with 2nd Row Hi-Line Armrests fitted, may report that the Silver Disc's which are fitted into the base of the cupholders have become detached. The attached file details the part

Cause:

Over a period of time in Service the adhesion has deteriorated

Action:

In the few cases reported, Retailers are having to replace the whole Armrest for this concern, when the disc's can simply be stuck down again by applying a small spot of Superglue - (STC50546) or equivalent to the underside of the disc.

Range Rover (L405) & Range Rover Sport (L494) Hi-Line Rear Centre Arm rest Cup holder Disc's

