



# Service Bulletin

File in Section: -

Bulletin No.: 16-NA-233

Date: July, 2016

## INFORMATION

**Subject:** Information on Accessory Fog Lamp Kit Missing Wire Harness

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2016	2017			All	All

<b>Involved Region or Country</b>	North America
-----------------------------------	---------------

The 2016 and 2017 Chevrolet Equinox does not have a necessary wire (circuit #1317) between the Body Control Module and the Underhood Electrical Center. The Fog Lamp Kit (P/N 23386622) does not contain this missing circuit.

The Wire Harness Kit, (P/N 84140224) (available through Service Parts), contains the wire necessary to complete the circuit. The installation of the Fog Lamp Kit (23386622), and the extra wire harness (84140224), are both addressed in the Installation Instruction (84140226).

### Parts Information

Description	Part Number	Qty
Wire Harness Kit	84140224	1

<b>Version</b>	1
<b>Modified</b>	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION