



RECREATIONAL VEHICLE SERVICE CAMPAIGN

March 28, 2017

SERVICE ADVISORY 17-280

«Dealer_name»
ATTN: Service Manager
«Street»
«Street_2»
«City», «State» «Zip»
«Country»

Dear «Dealer_name»,

Reason for this campaign It has been determined some 2017 Hideout 308BHDS and 281DBS models were built without the 4 inch rotaire vent installed in the bedroom wall. The repair is to add a vent in the wall in the bedroom and pull the existing duct out of the lavatory base and connect it to the added vent.

The campaign population includes:

**2017 Hideout Fifth Wheels, Models 308BHDS and 281DBS
Serial Number Range: H7208819 - H7208938**

Our records indicate unit(s) sold or in your present lot inventory fall within this range, which will require inspection. **Important:** Please complete the service campaign on these units before retail delivery. Our records indicate the following unit serial number(s) are presently in your inventory or have been sold:

«VIN1» «VIN2» «VIN3»
-- Serial numbers with '*' have been retail sold --

We apologize for any inconvenience this situation may cause and greatly appreciate your cooperation. Should you have any questions or concerns regarding this correspondence or the enclosed Service Advisory, please contact us at: **(866) 273-1454**

Sincerely,

KEYSTONE RV COMPANY

Rick Deisler
Vice President Service Operations

**PO Box 2000 Goshen, IN 46527-2000
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.kestonerv.com**