

## Engine Rattles at Startup

### AFFECTED VEHICLES

2013–16 Accord L4 and 2015–16 CR-V

**EDITOR'S NOTE:** This article replaces the one posted in **November 2016** to extend the article's shelf life. The issue(s) covered are still being addressed.

Does the engine rattle at startup for about **1 to 3 seconds**? What's happening is the lock pin inside the VTC actuator isn't holding the actuator properly. This lets the vane turn within the housing, causing a short rattle at startup.

Currently there aren't any countermeasures for the market, so **do not** replace the VTC actuator at this time. It's very unlikely that doing so will fix this concern.

We're anticipating a service bulletin with troubleshooting and repair info in the near future.