

## ACC, Collision Mitigation Braking System™, and Road Departure Mitigation Indicators On with DTC P2583-76

### AFFECTED VEHICLES

2017 CR-V (EX and above)

Some early production vehicles undergoing PDI or coming in with low mileage may have this issue:

- The ACC (Adaptive Cruise Control), Collision Mitigation Braking System, and Road Departure Mitigation indicators are on.
- DTC P2583-76 (temporary stop of integrated driver support system [misalignment millimeter wave radar]) is set.
- The driver information interface shows **Adaptive Cruise Control Problem**, **Collision Mitigation System Problem**, and **Road Departure Mitigation System Problem** messages.



From our investigation, we know this issue was caused by the factory's radar aiming process, which has since been improved.

To fix a vehicle with this issue, follow the service information procedure to aim the millimeter wave radar, then clear the DTC. There's no need to replace the radar.