

QUARANTINE NOTICE

Reference number:	QN-01-0056	Issued: 24 March, 2017
Subject:	Possible missing fuel line heat deflector	
Model(s):	V12 Vantage S and Vanquish	
VIN Range:	Refer to the list of applicable VIN published separately.	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Note: *It is possible that some vehicles that are in the affected VIN list for this Quarantine are now registered and given to a Customer. Make sure that you do a check of the Online Dealer Warranty (ODW) database to make sure that all necessary work is done to every vehicle.*

Reason for this Quarantine Notice

Because of an error during manufacture, it is possible that some of the vehicles in the affected VIN list do not have the heat deflector installed for the fuel line.

When you do the PDI on a vehicle in the list of affected VINs, examine and if necessary, do the Workshop Procedure below to install the heat deflector.

Workshop Procedure

WARNING: THE EXHAUST SYSTEM CAN BE VERY HOT AFTER OPERATION AND CAN CAUSE INJURY. LET THE EXHAUST SYSTEM BECOME COOL BEFORE YOU DO WORK.

1. Lift the vehicle and make it safe.
2. Refer to Figure 1 and examine the area at the corner of the floor pan where the fuel pipe goes into the engine bay.
3. If the heat deflector (1) is installed, you do not need to do more work. If the heat deflector (1) is not installed, do the steps that follow.




Figure 1

4. Put the heat deflector (1) in position.
5. Install and torque the two M6 attachment screws (2) to 9 Nm.

Part Data

Description	Part Number	Quantity
Heat deflector, front floor	ED33-11399-AA	1
M6 x 16 screw, flanged head	703265	2

Warranty Data**Procedure and Labour Time**

Description	Model	Task	Labour Time
Do a check to confirm that the heat deflector is installed. If necessary, install the heat deflector.	V12 Vantage S Vanquish S	Examine	Complete during PDI
		Repair	0.05 hours

If you have any questions related to this Quarantine Notice, please contact: Aston Martin Technical Services on: +44 (0) 1926 644720, email: askamtech@astonmartin.com,
Or contact your After Sales Manager.

The English version of this Quarantine Notice is written in Simplified Technical English to ASD-STE100™.