Mazda North American Operations Irvine, CA 92618-2922



REFERENCE NO: RF-17-05 DATE: July 11, 2017

SUBJECT: 2017 CX-5 AND CX-9 – INCORRECT CONTROLLER PROGRAMMING INSTRUCTIONS WITH ACCESSORY REMOTE START KIT C960-V7-620

There is a minor error with the Controller Programming instructions included with the accessory remote start kit C960-V7-620. In the current "Registration (programming) of the controller" instructions, step 5 shows an incorrect image. The function button is the lower button. A revised set of instructions are available in the Accessory E catalog and will be included in all kits at the next revision point.

