



Service Bulletin

PRELIMINARY INFORMATION

Subject: PQC Restriction Allison LCT1000 Transmission Valve Body RPO MW7 Has Ended

Models: 2015-2016 Chevrolet Silverado
2015-2016 GMC Sierra
Equipped with Allison LCT1000 Transmission RPO MW7

This PI was superseded to end the part restriction. Please discard PIP5224C.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The part restriction on the Allison LCT1000 transmission valve body P/N (24262535) RPO (MW7) has ended.

Recommendation/Instructions

Engineering would like to thank all the dealers that participated in the restriction program.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION