



Service Bulletin

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Exhaust Heat Exchanger Coolant Leak

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2016	2017	All		1.8L LKN	N/A


Involved Region or Country	North America
Additional RPO/s:	(1.8L) LKN
Condition	Smoke from exhaust system, coolant loss.

Correction

When Pressure testing the coolant system to isolate a coolant loss concern, remove the Exhaust front pipe assembly (2) from the Exhaust Heat Exchanger assembly (1) and check it for signs of internal coolant leakage.

If an internal leak is found in the Exhaust Heat Exchanger, replace and retest for system leakage.

Exhaust Heat Exchanger shown below (#1)



Version	1
----------------	---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION