



# Preliminary Information

PIT5321A Normal Characteristic - Missing Underhood Trim At Front Left Fender Area

**Models**

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2015 - 2016	All	All	All	All
GMC	Canyon	2015 - 2016	All	All	All	All


**Supersession Statement**

PIT5321 updated to PIT5321A to add 2016 model year.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

**Condition / Concern**

A dealer or customer may report that a trim piece is missing from the left front of the engine compartment where the fender and radiator support meet.



A dealer may call GM TAC or ParTech because they cannot find a replacement part for this item.

**Recommendations / Instructions**

The upper intake air baffle is present on the right side to protect the engine air filter inlet. Since no engine air inlet exists on left side, no baffle was used there.

Make no repair attempts or modifications to the vehicle, this is built to design intent.

**Customer Information**

Please communicate to the customer this condition is a normal build characteristic of their vehicle. It will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message  
Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



©2016 General Motors. All Rights Reserved.