



Preliminary Information

PIP5475 Vibration 70-60 MPH 6th gear deceleration manual transmission only

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Camaro ZL1	2017	All	All	LT4	MJK
Involved Region or Country	North America					
Condition	Some customers may comment on a vibration on deceleration in 6th gear only most noticeable at speeds of 70-60 mph. Vibration can be felt in the floor, seat, console and steering wheel. If a pico scope is used it presents at about 46 Hz.					
Cause	Currently under investigation					

Correction:

Concern will only be present in 6th gear on deceleration with the clutch pedal in the up position.

If the clutch is depressed and the concern is gone then the likely cause is related to the transmission main shaft and a repair is being validated. Do not attempt any repairs at this time.

If the clutch is depressed and the concern remains the same or in 5th gear during the same speed range please continue with published vibration diagnosis in service information.

Version History

Version	1
Modified	

